

## Challenge

### Issue

Severe marine corrosion within pipe suction throat led to corrosion/erosion damage and a hole in pipe, reducing lift pump effectiveness.

### Goals

Repair and protect pipe to avoid new pipe section purchase.

### Root Cause

High flow of raw seawater caused the nickel aluminum bronze pipe column to erode and corrode.



Pipe section after hot water pressure wash.

## Solution

### Preparation

- Hot water pressure wash.
- Grit blast to Sa 2.5 with 3 mil (75 µm) angular profile.

### Application

- Hole was patched with **ARC 858** and steel mesh at internal and external sides of hole.
- Covered external and internal faces with **ARC 858** and then top-coated with three coats of **ARC SD4i** to internals. Two coats to externals.




Pipe hole on left and patch section on right.

## Results

### Client Reported

Customer satisfied with repair and the performance of the coatings. The repaired solution continued in service without failure.

Customer avoided purchase of new pipe section and has now elected to coat the sea water lift pump as well.



Completed pipe repair and internal/external coating with **ARC 858** and **ARC SD4i**.