

## Challenge

### Issue

Existing FRP\* linings fail in <5 years causing corrosion and chemical attack. Weld repair and relining does not meet maintenance cycle requirements.

### Goals

- Achieve >5 years of service life with no corrosion/chemical attack to fan assembly

### Root Cause

Acid vapors attack FRP coating, exposing 304 SS impairing performance of fan.

\*Fiberglass Reinforced Polymer



Inside the housing after FRP removal

## Solution

### Preparation

- Hot water pressure wash 190°F (85°C)
- Grit blast to Sa 2.5 with 3 mil (75 µm) angular profile

### Application

1. Apply 2 coats of **ARC S4+** @ 20 mils (500 µm) wft/coat with total DFT of 40 mils (1000 µm)
2. High voltage spark test @ 100 v/mil (4 v/µm)



ARC S4+ applied on a housing

## Results

### Client Reported

- Inspection at 9 months rated coating in superior condition
- Based on comparison to FRP at 9 months, **ARC S4+** is expected to exceed 5-year goal



Nine month inspection of S4+ shows high gloss finish remains